

- Mechanical services in sunspace

No heating
No air-conditionning

- Floor type

Concrete floor on metal structure

- Floor covering

None

Monitoring 1995-1997

The results are satisfying on ecological and social point of view, even if energy is slightly below the simulation

Inhabitants behaviour :

- Heating often higher than design temperature
- Better use of solar devices, shading, apertures



Glazed sunspaces and transparent insulation



Greenhouse detail

Greenhouse facing South

